



**IDE Removable Pcb Instruction Manual Rev:B3**

**Model: TW-710**

LED Display Board





Connector CN2 for TW-711 connector CN2




LED1 - Power LED \_Green LED  
 LED2 - Access and HDD fail Bi-color LED \_Green -Access \_RED-HDD ERR

**Model: TW-711**



Connector CN2 for TW-710 connector CN2



Screw hold fix **NO.1** for IBM, SEAGATE, QUANTUM, FUJITSU HDD.

Screw hold fix **NO.2** for MAXTOR HDD


Screw hold fix **NO.3** for WESTEN DIGITAL HDD

**WHERE TO BUY**

<http://www.rackmountnet.com>  
 email: [sales@rackmountnet.com](mailto:sales@rackmountnet.com)

2372 Qume Dr, Suite E, San Jose, CA 95131  
 Call us at Toll Free: 1-866-955-0598


Model: TW-712



Screw hold fix **NO.1** for IBM, SEAGATE, QUANTUM, FUJITSU HDD.

Screw hold fix **NO.2** for MAXTOR HDD

Screw hold fix **NO.3** for WESTEN DIGITAL, HDD



**External LED Display Status (Bi-Color GREEN and RED in one)**

HDD Power ON - GREEN

HDD Access - Orange and GREEN Flashing

HDD Fail - RED

\* This version is support CS ( Cable Select ) Function.

**WHERE TO BUY**

<http://www.rackmountnet.com>  
 email: [sales@rackmountnet.com](mailto:sales@rackmountnet.com)

2372 Qume Dr, Suite E, San Jose, CA 95131  
 Call us at Toll Free: 1-866-955-0598